



Photo 1: Southern tank area prior to removal (facing east)





Photo 2: Removal of southern tank (facing northwest)







Photo 3: Southern tank area after tank removal (facing north)





Photo 4: Southern and northern tank areas after removal of northern tank (facing north)







Photo 5: Northern tank after removal (facing west)





Photo 6: South tank area after excavation of sewage-like contents to visually clean soil (facing north)

